

DROPS Area 6 Weekly Checklist

Date of Report: 04/03/2010

Area 6: Lower Substructure and BOP Deck				
Equipment	Photo Ref	~ ×	Initial	Comment / Non Conformance
Shacker Package				
Mud bilge (return d	litch) wash out fee	d pipe		
Check that pipe U clamps are secured with lock nuts or lock washers.	6.21.1			Bolt/s have no lock nut/s or safety pin/s
Wing platform gual	rdrails			
Check that all bolts or pins are in place and properly secured.	6.21.10			Bolts missing
Wing platform grat	ing			
Check grating is properly secured with clips and lock nuts or lock washers.	6.21.11			
Wing platform draw	v section			
Check that draw section is properly secured with pins and safety pins in place. Check that grating is properly secured to draw section. Check that guardrails are properly secured.	6.21.12			
Wing platform stair	′s			
Check that stairs are properly secured with pins and safety pins in place. Check that no slip tiles are properly secured to stairs. Check that handrails are properly secured.	6.21.13			