



DROPS Area 1 Corrective Actions Register

Date of Report: 04/03/2010

Ref	Equipment / Area	Fastening Method	Tag Number	Risks	Followup Action Required	Date closed
Area 1: Crown and Upper Mast						
1.1.02	Crown Block Assembly	Lock Wired Bolt Head		Medium		
1.1.03	Access Ladder (Section from Crown to Monkey Board Off Drillers Side)	Bolts and nuts		Medium	Bolts To Short	
1.1.04	Access Ladder (Section from Crown to Monkey Board Drillers Side)	Nylock		Medium	Bolts To Short	
1.1.10	Crown Access Hatch (Off Drillers Hatch)			High	Hatch Cover Missing	
1.1.11	Crown Access Hatch (Drillers Hatch)			High	Hatch Cover Missing	
1.1.19	Cable Trays (Crown)	Bolts and nuts		Medium	Cable Ties Missing	
1.1.22	Tpo Drive Bumper Block	Bolts and nuts		Medium	Safety Wire/Sling/Chain Missing	