











## DROPS Area 1 Photo Log Reference

Date of Report: 04/03/2010

Area 1: Crown and Upper Mast			Area 1: Crown and Upper Mast		
Drops ID	Equipment / Area	Notes	Drops ID	Equipment / Area	Notes
1.1.10	Crown Access Hatch (Off Drillers Hatch) 	There is no safety hatch in place	1.1.14	Highline Standoff Sheeves X 2 (Off Drawworks Side) 	Check nuts bolts are secure, and lock wire is in position
1.1.11	Crown Access Hatch (Drillers Hatch) 	There is no safety hatch in place	1.1.15	Personell Access Ramp Sheeves X 2 (Drawworks Side) 	Check nuts bolts are secure, and lock wire is in position
1.1.12	Strip Lighting (Crown) 	Check nuts bolts are secure, and safety wires are in place	1.1.16	Greese Lines Securing Brackets (Crown) 	Check bolts are secure, and clamp is in place
1.1.13	Vent Pipe Connection 	Check nuts bolts are secure	1.1.17	Aircraft Beacon light (Drawworks Side) 	Check nuts and bolts are secure and safety wire is attached